Kinetic analysis of phase transformations during continuous heating: Crystallization of glass-forming liquids

O.S. Houghton*

Materials Research Laboratory, Massachusetts Institute of Technology, 77 Massachusetts Avenue, Cambridge, Massachusetts, 02139, USA

*Corresponding author address: oshough@mit.edu

Abstract

Phase transformations are widely studied using continuous-heating experiments. In isothermal studies, their kinetics are often described using the Johnson-Mehl-Avrami-Kolmogorov (JMAK) rate equation. For continuous-heating studies, the same analysis has only been applied numerically. Here, a JMAK rate equation for phase transformations during continuous heating is derived. The equation is applied to the crystallization of glass-forming liquids with different kinetic behaviors and validated by comparison to experimental data and numerical simulations for the crystallization of glassy Fe₈₀B₂₀ (at.%). Kissinger's method of analyzing crystallization kinetics is subsequently justified, and it is shown that the non-Arrhenius temperature dependence of crystal growth rates in glass-forming liquids can be better determined by using the present model to fit the peak position, shape and height for a series of crystallization exotherms. The implications of these analytical expressions for the design and development of glass-forming systems for a broad range of applications are considered, and the application of this JMAK rate equation to other transformations during continuous heating is explored.

1. Introduction

Metallic, organic, inorganic and hybrid glasses have been objects of much scientific and technological interest [1, 2]. Understanding crystallization kinetics in such systems is critical to the development of high-performance glassy materials. To form a glass upon slow cooling, necessary to form thick glassy sections by casting, crystal nucleation or crystal growth rates must be low [3,4]. Though it is now possible to bypass this constraint on size by additive manufacturing or thermoplastic forming [5], heating and cooling of the glassy state after its formation risks crystallization. The need to determine crystal growth rates extends beyond processing to the technological function of certain glasses — for phase-change applications, fast switching between the crystalline and glassy phases requires rapid crystal growth during continuous heating while maintaining the ability to form a glass on cooling [6,7].

Phase transformations such as crystallization in glass-forming systems have been widely studied using continuous-heating experiments. Compared to isothermal experiments, continuous heating studies are fast, widen the temperature range in which crystallization can be measured, enable the study of fast transformations, and often mimic production processes or thermal treatments in their proposed application [6,8,9].

Although continuous-heating studies are easily performed across a wide range of heating rates, analysis of this data has required numerical simulations to fit the shape and position of crystallization exotherms and extract intrinsic material properties based on the isothermal Johnson-Mehl-Avrami-Kolmogorov (JMAK) rate equation derived over 80 years ago [7,10–12]. Numerical approaches are powerful in their ability to model complex scenarios, but analytical equations enhance the description of physical behavior and form the basis for parametric modelling. Models of this kind are computationally efficient, readily fitted to experimental data, and can form the basis for constraints in the design of high-performance materials [13]. Despite the prominence of continuous-heating experiments in the study of phase transformations, an analytical equation to describe these transformations on continuous heating has not been reported.

2. A JMAK equation for phase transformations during continuous heating

For an isothermal phase transformation, the JMAK rate equation describes its evolution with time assuming that:

- 1. there is spatially random nucleation,
- 2. the growth rate of the new phase is dependent only on temperature and not on time,
- 3. the transformation rate dX/dT does not depend on thermal history, but only the fraction transformed *X* and *T*,
- the growth rate of the new phase is not limited by the removal of heat from the interface [14,15], such that the temperature of the interface does not substantially deviate from the sample as a whole.

The transformed fraction X_{iso} at time *t* during an isothermal hold at a given temperature is then given by [8,16,17]:

$$X_{\rm ISO}(t) = 1 - \exp(-(Kt)^n),$$
(1)

where K is a temperature-dependent kinetic coefficient, and n is the Avrami exponent. The form of K and the value of n depends on the nature of the phase transformation. For crystallization, the exponent n typically varies between 1 and 4 depending on whether: crystallization is on a fixed number of randomly dispersed nuclei or there is ongoing generation of nuclei at a fixed or decreasing rate, the nature of nucleation sites, and on whether crystal growth is one-, two- or three-dimensional [17].

During continuous-heating experiments performed using calorimetry, as the sample transforms, heat is evolved which can be measured as an exotherm on a thermogram. At any instant, the height of the peak is proportional to dH/dt, which can be assumed proportional to dX/dt [18].

By considering a continuous-heating scan as a cycle of a small instantaneous temperature rise followed by a short isothermal hold, then the fraction transformed X at a given temperature T is given by:

$$\int_0^X \frac{\mathrm{d}x}{(1-x)[\ln(1-x)]^{\frac{n-1}{n}}} = \frac{n}{\Phi} \int_0^T K(T') \,\mathrm{d}T',\tag{2}$$

where it is assumed that there is no pre-existing transformed fraction, and the sample is heated from 0 K to *T* at a constant heating rate Φ .

Applying Eq. 2 to continuous heating studies requires that K(T) shows a single, smooth temperature dependence [8]. The case where a sample contains a fixed number of nuclei which are randomly dispersed, and that 3D spherical growth occurs on them at a constant rate with respect to time (n = 3) is specifically considered. Under these assumptions, the kinetic coefficient takes the form:

$$K(T) = \left(\frac{4}{3}\pi N\right)^{\frac{1}{3}}U(T),\tag{3}$$

where N is the effective number of nuclei per unit volume and U(T) is the temperaturedependent growth rate. For crystallization of a glass, where continuous normal growth occurs and the rate is limited by mobility at the crystal-liquid interface [14,15], then U is given by [16]:

$$U(T) = \frac{fk_BT}{3\pi a_0^2 \eta} \left[1 - \exp\left(\frac{-\Delta G}{RT}\right) \right],\tag{4}$$

where ΔG is the free energy difference between the liquid and crystal, a_0 is the average atomic diameter, η is the viscosity of the liquid, and f is the fraction of active sites at the crystal-liquid interface; R and $k_{\rm B}$ have their usual meanings.

At low Φ , where crystallization occurs at lower temperatures and over a narrow temperature range, ΔG is large such that the temperature dependence is dominated by the viscosity. Assuming the viscosity of the liquid is well-described by the Vogel-Fulcher-Tammann (VFT) model [19–21] in the temperature region of interest:

$$(-\ln(1-X))^{\frac{1}{3}} = \frac{1}{\Phi} \left(\frac{4\pi}{3}N\right)^{\frac{1}{3}} \left(\frac{fk_B}{3\pi a_0^2 \eta_{\infty}}\right) F(T),$$
(5)

where:

$$F(T) = \int_{T_0}^{T} T' \exp\left(-\frac{D^* T_0}{T - T_0}\right) \, \mathrm{d}T',\tag{6}$$

$$F(T) = \frac{1}{2} \left[T^2 - T_0^2 + D^* T_0^2 - D^* T_0 T \right] \exp\left(-\frac{D^* T_0}{T - T_0}\right) - \frac{D^* T_0^2 (D^* - 2)}{2} \operatorname{Ei}\left(-\frac{D^* T_0}{T - T_0}\right).$$
(7)

Here, $\operatorname{Ei}\left(\frac{D^*T_0}{T-T_0}\right)$ is the exponential integral, D^* and T_0 are fitting parameters dependent on the composition of the glass-forming liquid, and η_{∞} is the high-temperature limit of viscosity. Using the results of Abramowitz and Stegun [22], the general result is implicitly obtained:

$$X(T,\Phi) = 1 - \exp\left[-\left(\frac{\alpha \kappa T}{2\Phi}\right)^n\right],\tag{8}$$

where:

$$\alpha = \left[1 - D^* \frac{T_0}{T} + (D^* - 1) \left(\frac{T_0}{T}\right)^2 + \frac{(D^* - 2)T_0(T - T_0)}{T^2} \times \frac{\left(\frac{D^* T_0}{T - T_0}\right)^2 + 4.04 \left(\frac{D^* T_0}{T - T_0}\right) + 1.15}{\left(\frac{D^* T_0}{T - T_0}\right)^2 + 5.04 \left(\frac{D^* T_0}{T - T_0}\right) + 4.19}\right].$$
(9)

Since $K(T) \propto U(T)$ for crystallization on a fixed population of nuclei, Eqs. 8 and 9 represent the crystallized fraction for one-, two- and three-dimensional crystal growth on a fixed population of nuclei during continuous heating. A full description of the possible values that the exponent *n* can take for various conditions is provided in ref. [17].

3. Studying crystallization of a metallic glass

In metallic glasses (MGs), it is desirable to avoid crystallization on slow cooling to cast thick sections, and to have a large window between the glass-transition temperature T_g and the peak crystallization temperature T_x on continuous heating to ensure thermal stability and facilitate thermoplastic forming [5,23].

For the binary metallic glass $Fe_{80}B_{20}$ (at.%), Greer thoroughly assessed and numerically modelled its crystallization kinetics during continuous heating [12]. Not only is this glassforming system of technological interest as a soft-magnetic material [1], but its crystallization behavior meets very closely the criteria for the present analysis to be valid. Over the temperature range of crystallization, Greer suggests that U(T) shows Arrhenius temperature dependence [12]. For Arrhenius behavior of this kind, Eq. 6 simplifies to:

$$F(T) = \int_0^T T' \exp\left(-\frac{E_{\eta}}{RT}\right) \, \mathrm{d}T',\tag{10}$$

where E_{η} describes the activation energy for viscous flow. Solving this equation, the parameter α becomes:

$$\alpha = 1 - \left(\frac{\left(\frac{E_{\eta}}{RT}\right)^2 + 3.04\left(\frac{E_{\eta}}{RT}\right)}{\left(\frac{E_{\eta}}{RT}\right)^2 + 5.04\left(\frac{E_{\eta}}{RT}\right) + 4.19}\right),\tag{11}$$

which can also be obtained by taking Eq. 9 in the limit of $T \gg T_0$ for which $E_{\eta} = RT_0 D^* [1 - (T_0/T)]^{-1}$.



Figure 1. Experimental results for as-spun $Fe_{80}B_{20}$ ribbons continuously heated at rates between 10 and 80 K min⁻¹ reproduced from ref. [12] compared to numerical models performed in ref. [12] and the Arrhenius model described by using Eq. 8 and 11 using values for K_0 and E_η reported in ref. [12].

Using the measured values for E_{η} and the pre-factor for *K* obtained by Greer, Eq. 8 can reproduce the peak shape and position for continuous-heating scans at different rates performed on as-spun Fe₈₀B₂₀ ribbons (Figure 1): this analytical model shows good agreement with previous experimental and numerical models [12]. In Figure 1, Eq. 8 underestimates the experimentally observed T_x by 4–6 K. Differences between experimental and model thermograms could be partly attributed to the boundary conditions of integration, the assumption of Arrhenius behavior and ellipsoidal growth [12]. Differences between numerical and this analytical model are primarily due to the assumed boundary conditions of integration. When the peak shape and position of the four crystallization exotherms are fitted using a VFT model, an improved fit to the experimental data is obtained compared to the numerical and analytical Arrhenius models (Figure 2a). $Fe_{80}B_{20}$ has a finite value of T_0 which suggests deviations from Arrhenius behavior are observed, and are detectable over the width of a crystallization exotherm when the peak shape is fitted using the present analysis.



Figure 2. (a) Experimental results for as-spun Fe₈₀B₂₀ ribbons continuously heated at rates between 10 and 80 K min⁻¹ reproduced from ref. [12] are compared to analytical calculations performed using Eqs. 8 and 9 with values for K_0 reported in ref. [12] and D^* and T_0 values of 684 and 40 K, respectively. This combination of D^* and T_0 corresponds to an average E_η of 241 kJ mol⁻¹ over the temperature region of interest. (b) shows comparison of experimental results with the crystal growth model accounting for viscous decoupling [24] (Eqs. 8 and 24) and the VFT model for viscosity with D^* and T_0 values of 94 and 190 K, respectively.

4. Factors affecting resistance to crystallization

The present work highlights that the purpose of many numerical models has been to determine the value of α (Eqs. 9 and 11) by varying the temperature dependence of viscosity, the effective density of nuclei *N* and the pre-factor for crystal growth. At heating rates used in conventional calorimetry, the correction for the effect of thermodynamics on crystal growth rates is negligible such that the heating rate dependence of crystallization is dominated by the temperature dependence of viscosity [24,25]. The temperature dependence of viscosity is described by the fragility of the liquid m [26], which for VFT kinetics is given by:

$$m = \frac{d \log \eta}{d(\frac{T_g}{T})} = \frac{D^* T_0}{\ln 10} \frac{T_g}{(T_g - T_0)^2}.$$
 (12)

For low heating rates, where T_x lies close to T_g , the effective activation energy for viscous flow E_η increases as the liquid becomes more fragile (higher *m*). This corresponds to a lower resistance to crystallization on heating. With increasing E_η , the value of T_x can only be maintained by reducing the value of *N* (Figure 3a,b). When *N* remains unchanged, higher E_η (higher *m*) leads to an earlier onset of crystallization with a sharper and more intense exotherm [27].

The present analysis relies on the assumption referred to by Cahn as *site saturation* [28]; all nucleation occurs early in the reaction. In the present case, if N is large, then the effect of ongoing nucleation during continuous heating is negligible such that site saturation is effectively achieved. For many glass-forming systems, a substantial population density of quenched-in nuclei is formed during cooling to form a glass [29]. Site saturation is achieved such that Eq. 8 provides a reliable prediction of peak shape and position. As N increases (larger K_0 in ref. [12]), an earlier onset of crystallization is observed, T_x decreases but the shape of the exotherm is not substantially changed (Figure 3c,d). The effect of changing N on peak shape (Figure 3d) appears less significant than m (Figure 3b).



Figure 3. (a) Calculations of the crystallized fraction X on continuous heating at 10 K min⁻¹ for different E_{η} values and adjusting K_0 (proportional to $N^{1/3}$) to maintain a constant value of T_x . Data taken from ref. [12]. (b) Predicted shape of exotherm from (a) compared to numerical simulations performed in ref. [12]. (c) Calculations of the crystallized fraction X on continuous heating at 10 K min⁻¹ for different K_0 values used in ref. [12]. The values of K_0 used in the fitting have been adjusted to account for differences in definition between the present work and ref. [12]. (d) Predicted shape of exotherm from (c). (e) Calculations of the crystallized fraction X on continuous heating at 10 K min⁻¹ for fixed E_{η} values and K_0 but different values of n. (f) Predicted shape of exotherm from (e).

For exceptional glass-formers, or for liquids quenched to form a glass at high cooling rates, the as-quenched glass may contain a minimal number of nuclei [29]. For such samples, site saturation is not achieved and the effects of ongoing nucleation must be considered. For the case of constant nucleation rate on which three-dimensional crystal growth occurs, the kinetic coefficient takes the form:

$$K(T) = \left(\frac{\pi N}{3}\right)^{\frac{1}{4}} I^{1/4} U^{\frac{3}{4}},$$
(13)

where I is the steady-state nucleation rate. The effects of transient nucleation are assumed to be minimal as a population of embryos is inherited from quenching and prior temperature steps during continuous heating [12,30]. When the system necessitates that K takes the form of Eq. 13, there is no longer a single activation energy; a precise solution of Eq. 2 is best achieved numerically.

When N is kept fixed, and K is adjusted only for geometric differences between 1D, 2D and 3D crystal growth, decreasing n leads to a subtle shift in T_x to lower temperatures. The peak becomes broader and less intense (Figure 3e,f) due to the expected differences in the geometry of crystal growth.

5. Kissinger method applied to crystallization

For most glass-forming liquids, a substantial population density of nuclei exists from quenching or is generated during continuous heating at low Φ before the onset of the crystallization exotherm — the effective population density of nuclei N is high such that *site saturation* condition is achieved.

Kissinger's method to study crystallization as a function of heating rate has been widely adopted [31]. On this plot of $\ln(\Phi/T_x^2)$ versus $1/T_x$, the gradient is equal to $-E_x/R$ where, T_x is the peak of the crystallization exotherm and E_x is the effective activation energy for crystallization. Using Eq. 8, it is possible to advance the original validation of the Kissinger method for crystallization during continuous heating by Henderson [8], defining the exact form of the curve:

$$\ln\left(\frac{\Phi}{T_x^2}\right) = \ln\left(\frac{1}{2}\right) + \ln\left(\frac{\alpha K}{T_x}\right) - n\ln(-\ln[1 - X(T_x, \Phi)]).$$
(14)

 T_x typically corresponds to a transformed fraction close to 63% (see Supplementary Material), such that the equation simplifies to the form:

$$\ln\left(\frac{\Phi}{T_{\rm x}^2}\right) = \frac{1}{3}\ln\left(\frac{\pi N}{6}\right) + \ln\left(\frac{fk_{\rm B}}{3\pi a_0^2}\right) + \ln\alpha - \ln(\eta),\tag{15}$$

for all Φ where $|\Delta G|$ is large. The first two terms are temperature-independent and the variation in α is typically small compared to the variation in η . Under these assumptions, the gradient of the Kissinger plot is then given by:

$$E_{\rm x}(T_{\rm X}) \approx RT_{\rm g} \ln 10 \frac{\mathrm{d}\log\eta}{\mathrm{d}(T_{\rm g}/T_{\rm X})} = mRT_{\rm g} \ln 10 \left(\frac{T_{\rm x}}{T_{\rm g}}\right)^2 \left(\frac{T_{\rm g}-T_{\rm 0}}{T_{\rm x}-T_{\rm 0}}\right)^2.$$
(16)

In the limit of $T_0 \ll (T_g, T_x)$ and a narrow range of Φ , E_x does not show any temperature dependence. With accurate determination of T_g and T_0 , it is possible to determine a value of *m* from a Kissinger plot, as implied in the work of Chen [25] and discussed by Henderson [8].

6. Effects of fragility and fast crystal growth

Though this method is specifically applied in this work to crystallization in metallic glassforming systems, the method is, in principle, applicable to a phase transformation in any system where JMAK kinetics are a valid description. Glassy materials that exhibit fast crystal growth are ideal materials for phase-change applications. For these systems, which are clearly fragile (m > 80 [6]), Ediger *et al.* highlight that crystal growth rates are decoupled from the viscosity of the liquid [24].

In a classical approach, the crystal growth rate varies with the mobility at the crystal-liquid interface. This is assumed proportional to the atomic diffusivity in the bulk liquid, which itself is assumed to be inversely proportional to the viscosity of the liquid. This allows application of the Stokes-Einstein relation to determine an expression for U. At high temperatures, these assumptions generally hold. As the temperature lowers, it is suggested that progressive decoupling of atomic diffusivity from viscous flow occurs, such that the atomic diffusivity is much higher than expected from the Stokes-Einstein relation [24]. The crystal growth rate should then be given by:

$$U(T) = \frac{a}{\tau_0} \left(\frac{\eta(T)}{\eta_0}\right)^{-\epsilon} \times \exp\left[-\frac{\Delta S_f}{R}\right] \left[1 - \exp\left(\frac{-\Delta G}{RT}\right)\right],\tag{20}$$

where *a* is the lattice spacing of the forming crystal, τ_0 is the structural relaxation time at the reference viscosity η_0 , ΔS_f is the entropy of fusion and ϵ is the empirical decoupling factor given by [24]:

$$\epsilon = 1.1 - 0.005m. \tag{21}$$

For many glass-forming systems, ϵ lies close to one such that its effect is not significant. For fragile systems, ϵ can become much lower than one having a substantial effect on predictions of crystal growth rate [6,24]. The VFT model for viscosity enables simple inclusion of this parameter in the present analysis. Using Eq. 20, a revised value of α takes the form:

$$\alpha = \frac{2(T-T_0)}{T^2} \left[1 - \frac{\left(\frac{\epsilon D^* T_0}{T-T_0}\right)^2 + 4.04 \left(\frac{\epsilon D^* T_0}{T-T_0}\right) + 1.15}{\left(\frac{\epsilon D^* T_0}{T-T_0}\right)^2 + 5.04 \left(\frac{\epsilon D^* T_0}{T-T_0}\right) + 4.19} \right].$$
 (24)

Eq. 24 and an appropriate expression for K in Eq. 8 can reasonably fit the crystallization exotherms for Fe₈₀B₂₀ at different heating rates (Figure 2b). Numerical simulations are not required to explore the effects of decoupling from viscous flow on the shape and form of crystallization exotherms. The effects of fragility can be determined using analytical methods; parametric modelling and fittings of experimental results are possible.

7. Characterization of devitrification in glasses

When crystallization of a glass during continuous heating exhibits a single temperature dependence, it is shown that the Kissinger method can then be applied. The resulting plot (Figure 4a) can be related to both the population density of nuclei and the temperature dependence of the crystal growth rate. For a glass-forming liquid whose crystal growth rate is well-described by Eq. 4, values for *N* and the effective activation energy for viscous flow E_{η} can be determined from the Kissinger plot using Eq. 15.

One can consider *N* as the population density of nucleation centers on which crystallization occurs. As such, it can represent the combined density of quenched-in nuclei, nuclei generated during annealing, or impurities that can behave as heterogeneous nucleants [33]. Assuming there is not substantial crystal growth upon these nucleation centers prior to measurement of the thermogram, the effects of impurities and thermal history on the position of T_x should be readily quantifiable using the present analysis. The value of the Avrami exponent can also provide important and complementary information about the nature of nucleation sites, as outlined by Christian [17].

In fitting the peak shape and position of the crystallization exotherm for a given heating rate Φ , it is possible to obtain crystal growth rates over a wider temperature range compared to the Kissinger method without the need for further experiments (Figure 4a). The shape and height of the crystallization exotherm provides important information about the non-Arrhenius temperature dependence which can be described using the VFT model in the present analysis — each combination of D^* and T_0 produces a unique exotherm (Figure 4b).



Figure 4. (a) Plot of $\ln(K/K_0)$ for the VFT model obtained by peak fitting in the present work, the Arrhenius model obtained by numerical fitting of the peaks and via the Kissinger method in ref. [12]. T_x data plotted using the Kissinger method in ref. [12] is also shown. The temperature ranges in which data is obtained by the Kissinger method and peak fitting methods for the same series of exotherms are shaded. (b) Plot of expected crystallization exotherms on heating at 10 K min⁻¹ for different combinations of D^* and T_0 that would correspond to an effective activation energy of 242 kJ mol⁻¹. Values of D^* are 684 ($T_0 = 40$ K), 247 ($T_0 = 100$ K) and 101.4 ($T_0 = 200$ K).

For Fe₈₀B₂₀, eutectic crystal growth occurs [12] and so the temperature dependence of the crystal growth rate does not solely depend on mobility at the crystal-liquid interface. D^* and T_0 parameters reported here only describe the local temperature dependence of U in this region of interest. For systems whose crystal growth rate is limited by mobility at the crystal-liquid interface, deviations in $\ln(K/K_0)$ from Arrhenius behavior, which can be detected using this peak fitting approach (Figure S1), are directly related to the fragility of the liquid.

This analysis focuses on thermograms measured at low heating rates, but ultra-fast (flash) calorimetry has become a powerful technique able to achieve continuous heating and cooling at rates exceeding 10^3 K s⁻¹. It enables mimicking of rapid solidification, study of degradationprone materials, glassy states with a minimal number of quenched-in nuclei and stochastic nucleation effects [29,30,32,34]. Compared to conventional calorimetry, crystallization is studied in flash calorimetry across a wider range of heating rates, for which E_x is typically not constant [6,34,35]. The Kissinger plot of T_x data collected using flash calorimetry hence reflects the curvature in $\ln(K)$. The equations derived in the present work are applicable to flash calorimetry studies, but there are limitations imposed by the assumed boundary conditions. At high heating rates, crystallization occurs at high temperature and over a wider temperature range. ΔG reduces in magnitude and varies substantially within this temperature range such that thermodynamic corrections are required before attempting a Kissinger plot of the kinetic component of U [6]. At even higher heating rates, the overlap of the crystallization exotherm and melting leads to incomplete crystallization, for which numerical simulations are required [6,7].

Though the primary focus of this work has been the fitting and characterization of experimental results to validate the analysis, a JMAK rate equation for continuous heating of this kind realizes opportunities to predict (with quantified uncertainty) the performance and key features of thermograms for glassy materials. Expressions for the critical cooling rate for glass formation have been established, but efforts to predict other key indicators of glass-forming ability, such as ΔT_x (equal to T_x-T_g) have been less successful [5]. The various equations within this work could enable improved prediction of crystallization behavior on continuous heating for a broad range of glass-forming systems.

8. Broader application to the characterization of transformations

The JMAK equation for continuous heating is potentially applicable to a broad range of phase transformations in different materials, as well as beyond materials science [36]. For phase transformations in materials, the assumptions for JMAK to be valid hold for polymorphic changes, discontinuous precipitation, eutectic and eutectoid reactions and interface-controlled growth amongst others [17]. Such transformations may be studied using calorimetry, or other techniques where transformed fractions are readily determined, such as, but not limited to dilatometry, thermogravimetric analysis and X-ray diffraction.

Isothermal heat treatments are a common post-synthesis step in the processing of highperformance materials. The advent of techniques such as additive manufacturing and flash sintering which have distinctly non-isothermal profiles can lead to distinctly different microstructures whose evolution cannot be described using a simple isothermal model. It is worthwhile considering the suitability of the present analysis to describe and model such processing techniques as a single scan or series of continuous heating scans. Physics-based parametric models of this kind are beneficial to the design of compositions that can produce the desired microstructures via these advanced manufacturing techniques.

9. Conclusions

A Johnson-Mehl-Avrami-Kolmogorov (JMAK) rate equation is derived to describe phase transformations during continuous heating. Applicable to a broad range of phase transformations, explicit expressions are derived for crystallization in glass-forming systems that show different kinetic behaviors. The expressions are shown to successfully model the crystallization behavior of the metallic glass $Fe_{80}B_{20}$ (at.%) and can fully justify the Kissinger method for studying crystal growth during continuous heating. These analytical expressions can be applied to understand and model the effects of kinetic fragility of the liquid, and enhanced mobility at low temperatures on the crystallization exotherms measured at different heating rates using this parametric model, it is possible to efficiently and more accurately determine the non-Arrhenius temperature dependence of crystal growth rates for a glass-forming liquid than by the Kissinger method alone. The derived expressions form an important link between material properties and phase transformation kinetics that could help facilitate fast and easy characterization and reliable prediction of performance and processability of glassy materials.

It is highlighted that similar expressions could be derived based on this model to characterize and predict the kinetics of other transformations which occur in a broad range of material systems.

Acknowledgements

It is a pleasure to thank Prof. A. Lindsay Greer for many useful discussions, critical reading of the manuscript and thoughtful suggestions, and Prof. Gregory B. Olson for allowing time to pursue this work.

Author Declarations

The author has no conflicts to disclose.

Data Availability

The data that support the findings of this work are available from the author upon reasonable request.

References

[1]	A.L. Greer, M.B. Costa, O.S. Houghton, Metallic glasses, <i>MRS Bulletin</i> , 48 1054–1061 (2023).
[2]	T.D. Bennett, S. Horike, J.C. Mauro, M.M. Smedskjaer, L. Wondraczek, Looking into the future of hybrid glasses, <i>Nat. Chemistry</i> , 16 , 1755–1766 (2024).
[3]	D. Turnbull, Under What conditions can a glass be formed? <i>Contemp. Phys.</i> 10 , 473–488 (1969).
[4]	D.R. Uhlmann, A kinetic treatment of glass formation, J. Non. Cryst. Solids 7, 337–348 (1972).
[5]	O.S. Houghton, M.B. Costa, A.L. Greer, Analytical approach to glass formation in casting, thermoplastic forming and additive manufacturing of metal alloys, <i>In Review</i> (2025).
[6]	J. Orava, A.L. Greer, B. Gholipour, D.W. Hewak, C.E. Smith, Characterization of supercooled liquid Ge ₂ Sb ₂ Te ₅ and its crystallization by ultrafast-heating calorimetry, <i>Nature Mater.</i> 11 , 279 (2012).
[7]	J. Orava, A.L. Greer, Fast and slow crystal growth kinetics in glass-forming melts, <i>J. Chem. Phys.</i> 140 , 214504 (2014).
[8]	D.W. Henderson, Thermal analysis of non-isothermal crystallization kinetics in glass-forming liquids, <i>J. Non-Cryst. Solids</i> 30 , 301–315 (1979).
[9]	C.R. Quick, P. Dumitraschkewitz, J.E.K. Schawe, S. Pogatscher, Fast differential scanning calorimetry to mimic additive manufacturing processing: specific heat capacity analysis of aluminium alloys, <i>J. Therm. Anal. Calorim.</i> 148 , 651–662 (2023).
[10]	M. Avrami, Kinetics of phase change. I. General theory, J. Chem. Phys. 7 1103–1112 (1939).
[11]	M. Avrami, Kinetics of phase change. II. Transformation-time relations for random distribution of nuclei, <i>J. Chem. Phys.</i> 8 , 212–224 (1940).
[12]	A.L. Greer, Crystallization kinetics of Fe ₈₀ B ₂₀ glass, <i>Acta Metall.</i> 30 , 171–192 (1982).
[13]	G.B. Olson, Designing a new material world, Science 288, 993–998 (2000).
[14]	G.S. Melling, D.R. Uhlmann, Crystallization and melting kinetics of sodium disilicate, <i>Phys. Chem. Glasses</i> 8 , 62 (1967).
[15]	P.J. Vergano, D.R. Uhlmann, Crystallization kinetics of germanium dioxide – Effect of stoichiometry on kinetics, <i>Phys. Chem. Glasses</i> 11 , 30 (1970).

[16]	K.F. Kelton, A.L. Greer, Nucleation in condensed matter, <i>Pergamon Materials Science, Elsevier</i> (2010) UK.
[17]	J.W. Christian, The theory of transformations in metals and alloys, <i>Pergamon Press, Elsevier</i> (1975) UK.
[18]	H. J. Borchardt, F. Daniels, The application of differential thermal Analysis to the study of reaction kinetics, <i>J. Am. Chem. Soc.</i> 78 , 41–46 (1957).
[19]	H. Vogel, Das Temperaturabhängigkeitsgesetz der Viskosität von Flüssigkeiten, <i>Physik. Z.</i> 22 , 645 (1921).
[20]	G.S. Fulcher, Analysis of recent measurements of the viscosity of glasses. J. Am. Ceram. Soc. 7, 339–355 (1925).
[21]	G. Tammann, W. Hesse, Die abhängigkeit der viscosität von der temperatur bie unterkühlten flüssigkeiten, Z. anorg. u. allg. Chem. 156 , 245–257 (1926).
[22]	M. Abramowitz and I.A. Stegun, Handbook of mathematical functions with formulas, graphs and mathematical functions, <i>Dover Publications</i> (1970) US.
[23]	J. Schroers, The superplastic forming of bulk metallic glasses. <i>JOM</i> 57 , 35–39 (2005).
[24]	M.D. Ediger, P. Harrowell, L. Yu, Crystal growth kinetics exhibit a fragility- dependent decoupling from viscosity, <i>J. Chem. Phys.</i> 128 , 034709 (2008).
[25]	H.S. Chen, A method for evaluating viscosities of metallic glasses from the rates of thermal transformations, <i>J. Non-Cryst. Solids</i> 27 , 257–263 (1978).
[26]	C.A. Angell, Formation of glasses from liquids and biopolymers, <i>Science</i> 267 , 1924–1935 (1995).
[27]	K.A. Jackson, D.R. Uhlmann, J.D. Hunt, On the nature of crystal growth from the melt, <i>J. Cryst. Growth</i> 1 , 1–36 (1967).
[28]	J.W. Cahn, Transformation kinetics during continuous cooling, Acta Met. 4 572–575 (1956).
[29]	J.E.K. Schawe, J.F. Löffler, Existence of multiple critical cooling rates which generate different types of monolithic metallic glass, <i>Nat. Commun.</i> 10 , 1337 (2019).
[30]	O.S. Houghton, A.L. Greer, Sample size effects in calorimetric studies of structural relaxation and crystallization of a gold-based metallic glass, <i>Acta Mater.</i> 288 , 120862 (2025).
[31]	H.E. Kissinger, Reaction kinetics in differential thermal analysis, <i>Anal. Chem.</i> 29 , 1702–1706 (1957).

[32]	A. Singh, Y. Kim, R. Henry, H. Ade, D.B. Mitzi, Study of glass formation and crystallization kinetics in a 2D metal halide perovskite using ultrafast calorimetry, <i>J. Am. Chem. Soc.</i> 145 , 18623–18633 (2023).
[33]	N.D. Campos Neto, C. Soares, F.S. Pereira, V. Bergamaschi, S.G. Antonio, M.J. Kaufman, M.F. de Oliveira, Glass forming ability and continuous-cooling-transformation (CCT) diagrams of Vitreloy 105 as function of cooling rate and oxygen concentration, <i>J. Non-Cryst. Solids</i> 528 , 119762 (2020).
[34]	O.S. Houghton, C. Ye, A.C. Twitchett-Harrison, S. Dutton, T.D. Bennett, A.L. Greer, Glass transition, liquid dynamics and thermal degradation in 2D hybrid halide perovskites, <i>Small</i> 250311 (2025).
[35]	S. Pogatscher, P.J. Uggowitzer, J.F. Löffler, In-situ probing of metallic glass formation and crystallization upon heating and cooling via fast differential scanning calorimetry, <i>Appl. Phys. Lett.</i> 104 , 251908 (2014).
[36]	K. Shirzad, C. Viney, A critical review on applications of the Avrami equation beyond materials science, <i>J. R. Soc. Interface</i> , 20 , 20230242 (2023).

Kinetic analysis of phase transformations during continuous heating: Crystallization of glass-forming liquids Supplementary Material

O.S. Houghton

The Kissinger plot of $\ln(\Phi/T_x^2)$ against $1/T_x$ requires accurate determination of T_x in terms of dX/dT. According to Borchardt [15], the peak of the crystallization exotherm at T_x corresponds to the maximum transformation rate:

$$\left. \frac{d^2 x}{dt^2} \right|_{T=T_{\rm x}} = 0. \tag{S1}$$

Using Eq. 8, we find:

$$\left(\frac{\mathrm{d}X}{\mathrm{d}t}\right) = \Phi \frac{\mathrm{d}X}{\mathrm{d}T} = n\Phi\left[-\ln(1-X)\right]\left[1-X\right]\left[\frac{\mathrm{d}\ln\left(\frac{\alpha KT}{2\Phi}\right)}{\mathrm{d}T}\right],\tag{S2}$$

$$\left(\frac{\mathrm{d}X}{\mathrm{d}t}\right) = \Phi \frac{\mathrm{d}X}{\mathrm{d}T} = n\Phi\left[-\ln(1-X)\right]\left[1-X\right]\left[\frac{\mathrm{d}\ln(\alpha)}{\mathrm{d}T} + \frac{\mathrm{d}\ln(U)}{\mathrm{d}T} + \frac{1}{T}\right].$$
(S3)

Calculating the second derivative yields:

$$\begin{pmatrix} \frac{d^{2}x}{dt^{2}} \end{pmatrix} = \Phi \frac{d}{dT} \left(\Phi \frac{dx}{dT} \right) = \Phi^{2} \frac{d^{2}x}{dT^{2}} = n\Phi^{2} \frac{d}{dT} \left[\left(\frac{\alpha KT}{2\Phi} \right)^{n} \exp \left[- \left(\frac{\alpha KT}{2\Phi} \right)^{n} \right] \left[\frac{d\ln(\alpha)}{dT} + \frac{d\ln(U)}{dT} + \frac{1}{T} \right] \right], \quad (S4)$$

$$\frac{d^{2}x}{dt^{2}} \Big|_{x=x_{p}} = n\Phi^{2} \left(\frac{\alpha KT}{2\Phi} \right)^{n} \exp \left[- \left(\frac{\alpha KT}{2\Phi} \right)^{n} \right] \frac{d}{dT} \left[\left[\frac{d\ln(\alpha)}{dT} + \frac{d\ln(U)}{dT} + \frac{1}{T} \right] \right] + n\Phi^{2} \left(\frac{\alpha KT}{2\Phi} \right)^{n} \left[\frac{d\ln(\alpha)}{dT} + \frac{d\ln(U)}{dT} + \frac{1}{T} \right] \right]$$

$$\frac{1}{T} \frac{d}{dT} \left[\exp \left[- \left(\frac{\alpha KT}{2\Phi} \right)^{n} \right] \right] + n\Phi^{2} \left[\frac{d\ln(\alpha)}{dT} + \frac{d\ln(U)}{dT} + \frac{1}{T} \right] \exp \left[- \left(\frac{\alpha KT}{2\Phi} \right)^{n} \right] \frac{d}{dT} \left[\left(\frac{\alpha KT}{2\Phi} \right)^{n} \right] = 0, \quad (S5)$$

$$\frac{d^{2}x}{dt^{2}} \Big|_{x=x_{p}} = -n\Phi^{2} \ln(1-X_{p}) \left[1 - X_{p} \right] \frac{d}{dT} \left[\left[\frac{d\ln(\alpha)}{dT} + \frac{d\ln(U)}{dT} + \frac{1}{T} \right] \right] - n\Phi^{2} \ln(1-X_{p}) \left[\frac{d\ln(\alpha)}{dT} + \frac{d\ln(\alpha)}{dT} + \frac{d\ln(U)}{dT} + \frac{1}{T} \right] \right] - n\Phi^{2} \ln(1-X_{p}) \left[\frac{d\ln(\alpha)}{dT} + \frac{d\ln(\alpha)}{dT} + \frac{d\ln(U)}{dT} + \frac{1}{T} \right] \left[1 - X_{p} \right] \frac{d}{dT} \left[\left(\frac{\alpha KT}{2\Phi} \right)^{n} \right] = 0, \quad (S6)$$

$$\ln(1-X_{p}) \left[1 - X_{p} \right] \left[\left[\frac{d^{2} \ln(\alpha)}{dT^{2}} + \frac{d^{2} \ln(U)}{dT^{2}} - \frac{1}{T^{2}} \right] \right] - n\ln(1-X_{p})^{2} \left[1 - X_{p} \right] \left[\frac{d\ln(\alpha)}{dT} + \frac{d\ln(U)}{dT} + \frac{1}{T} \right]^{2} - n\left[\frac{d\ln(\alpha)}{dT} + \frac{d\ln(U)}{dT} + \frac{1}{T} \right]^{2} \left[1 - X_{p} \right] \ln(1-X_{p}) = 0. \quad (S7)$$

Eq. S7 is satisfied when X_P takes the value of zero (no crystallinity), one (fully crystallized) or:

$$X_{\rm p} = 1 - \exp\left[-1 + \frac{1}{n} \left[\frac{d^2 \ln(\alpha)}{dT^2} + \frac{d^2 \ln(U)}{dT^2} - \frac{1}{T^2}\right] \left[\frac{d \ln(\alpha)}{dT} + \frac{d \ln(U)}{dT} + \frac{1}{T}\right]^{-2}\right].$$
 (S8)

For viscosity that shows near-Arrhenius behavior, and crystal growth rates not restricted by thermodynamic effects, we can take the limit that the temperature dependence of $\ln(\alpha)$ is small compared to $\ln(U)$ such that:

$$X_{\rm p} \approx 1 - \exp\left[-1 + \frac{1}{n} \left[\frac{d^2 \ln(U)}{dT^2} - \frac{1}{T^2}\right] \left[\frac{d \ln(U)}{dT} + \frac{1}{T}\right]^{-2}\right],\tag{S9}$$

where for large ΔG and n = 3:

$$\frac{d\ln(U)}{dT} = \frac{d}{dT} \left[\ln(T) - \frac{D^* T_0}{T - T_0} \right] = \frac{1}{T} + \frac{D^* T_0}{(T - T_0)^2},$$
(S10)

$$\frac{d^2 \ln(U)}{dT^2} = -\frac{1}{T^2} - \frac{2D^* T_0}{(T - T_0)^3},$$
(S11)

$$X_{\rm p} \approx 1 - \exp\left[-1 - \frac{2}{3} \left[\frac{(T_{\rm X} - T_0)}{D^* T_0}\right]\right] = 1 - \exp\left[-1 - \frac{2T_{\rm g}}{3m(T_{\rm X} - T_0)\ln 10}\right].$$
 (S12)

Eq. S12 yields $X_p = 0.636$ for Fe₈₀B₂₀, in good agreement with ref. [8].



Figure S1. Plot of 2^{nd} derivative of ln(K) with respect to 1/T for the VFT model obtained by peak fitting in the present work, the Arrhenius model obtained by numerical fitting of the peaks and via the Kissinger method in ref. [12]. The non-zero curvature of the VFT model is clearly shown.