PREPARED FOR SUBMISSION TO JINST

8<sup>TH</sup> INTERNATIONAL CONFERENCE ON MICRO-PATTERN GASEOUS DETECTORS 14-18 October 2024 Hefei, China

# Development of the high-rate capable DLC-RPC based on the current evacuation pattern

M. Takahashi,<sup>*a*,\*</sup> S. Ban,<sup>*b*</sup> W. Li,<sup>*c*</sup> A. Ochi,<sup>*a*,<sup>†</sup></sup> W. Ootani,<sup>*b*</sup> A. Oya,<sup>*b*</sup> H. Suzuki<sup>*a*</sup> and K. Yamamoto<sup>*c*</sup>

<sup>a</sup>Department of Physics, Kobe University,

1-1, Rokkodai-cho, Nada-ku, Kobe, 657-8501, Hyogo, Japan

<sup>b</sup>International Center for Elementary Particle Physics, The University of Tokyo,

Bunkyo-ku, Tokyo, 113-0033, Japan

<sup>c</sup> Department of Physics, The University of Tokyo, Bunkyo-ku, Tokyo, 113-0033, Japan

*E-mail:* m.takahashi@stu.kobe-u.ac.jp

ABSTRACT: The Resistive Plate Chamber using Diamond-Like Carbon electrodes (DLC-RPC) has been developed as a background tagging detector in the MEG II experiment. The DLC-RPC is planned to be installed in a high-intensity and low-momentum muon beam. This detector is required to have a detection efficiency of above 90 % with four active gaps in the muon beam due to the limitation of the material budget. In such an environment, the high current flowing through the resistive electrodes causes a voltage drop, which reduces the performance of the DLC-RPC. This voltage drop can be suppressed by implementing a current evacuation pattern, though discharges are more likely to occur near the pattern. Therefore the pattern must be covered by a protection cover made of an insulator. In this study, electrode samples with the current evacuation pattern and different widths of protection cover (0.2 mm and 0.8 mm) have been produced, and their performance and stability were measured. The detection efficiency of the single-gap for  $\beta$ -ray from a <sup>90</sup>Sr source was measured to be up to approximately 60 % in both electrode samples. The target efficiency can be achieved even with a drop of 100 - 150 V. On the other hand, after more than a dozen hours of operation, discharges suddenly occurred and the detector was prevented from further operation. These discharges created current paths on the spacing pillars. This serious problem must be investigated and solved in the future.

KEYWORDS: Gaseous detectors; Resistive-plate chambers

ArXiv ePrint: 2501.05128

<sup>\*</sup>Corresponding author.

<sup>&</sup>lt;sup>†</sup>Deceased.

## Contents

1	Introduction	1
2	DLC-RPC with current evacuation pattern	1
3	Experimental setup	2
4	Results and Conclusion	2

## 1 Introduction

A novel type of resistive plate chamber, based on diamond-like carbon (DLC) electrodes [1], is under development as a background tagging detector in the MEG II experiment [2]. This detector should have an ultra-low mass (less than  $0.1 \% X_0$ ) and a high-rate capability (up to  $3 \text{ MHz/cm}^2$ ), which needs to be operated in a high-intensity ( $7 \times 10^7$  /s) and low-momentum (28 MeV/c) muon beam. In addition, a detection efficiency above 90 % is required for minimum ionization particles in an active region of 16 cm in diameter. The number of active gaps is limited to up to four in order to fulfill the requirement of the material budget.

Reference [1] proposed strip-shaped current evacuation patterns to achieve a high rate capability with a scalable detector design. The small-size prototype chamber of the DLC-RPC was constructed to study this design [3]. However, we could not study it with this prototype because the gap thickness was non-uniform due to the technical problems of spacing pillar formation. Therefore, we constructed the other solder resist (Dynamask, Ethernal Tech. Corp.) that can make uniform pillars. The current evacuation pattern was implemented in this prototype detector. This paper describes the performance and operation stability of the prototype

## 2 DLC-RPC with current evacuation pattern

Figure 1 shows the DLC-RPC electrode with the current evacuation pattern. DLC was directly sputtered onto the 50 µm thick polyimide film. The conductive current evacuation pattern was implemented on the DLC layer and covered with the protection cover whose material is the same as the pillars. This pattern was formed by the lift-off process. Chromium was sputtered onto the DLC layer, followed by copper sputtering onto the chromium layer. This sandwich structure is motivated by the good adherence of chromium with DLC. This electrode has the pillars (~365 µm thick, 0.6 mm diameter, 2.5 mm pitch), the current evacuation pattern (0.1 mm width), and  $3 \times 3 \text{ cm}^2$  of the active region. The variation of the pillar thickness was measured to be below 10 µm. The surface resistivity of DLC was measured to be  $6 - 15 \text{ M}\Omega/\text{sq}$ . Different electrode samples with 0.2 mm and 0.8 mm widths of the protection cover were tested to investigate the width needed to avoid discharge. According to the results and discussions in Reference [1], the voltage drop will be down to 100 V at the expected operation voltage in the muon beam in this configuration.



**Figure 1**. Pictures and a schematic of the DLC-RPC electrode with the current evacuation pattern. (Left) Overview. (Center) Enlarged view of the strip structure. (Right) Cross-section of the strip structure.

### **3** Experimental setup

The electrode shown in Figure 1 was used as an anode electrode. A bare DLC sputtered polyimide was used as a cathode electrode, in which the surface resistivity of DLC was measured to be  $10 - 15 M\Omega/sq$ . These electrodes were placed facing each other to form the DLC-RPC gas gap. This gap was filled with  $C_2H_2F_4/SF_6/iC_4H_{10}$  (94/1/5). The signals were induced to an aluminum strip outside the gas gap, amplified by 38 dB, and then input to the DRS4 waveform digitizer [4].

## 4 Results and Conclusion

Figure 2 shows the performances of the DLC-RPC for the  $\beta$ -ray from a <sup>90</sup>Sr source. In this measurement, the  $\beta$ -ray was collimated with 2 mm in diameter and irradiated far from the conductive pattern to avoid instability due to the strip structure. The hit rate was O(1 kHz) at that time. The *n*-gaps efficiency can be estimated with the single-gap efficiency  $\epsilon_1$  by  $\epsilon_n = 1 - (1 - \epsilon_1)^n$ . The measured efficiency of 60 % is enough to reach a target efficiency of 90 % with four gaps. In addition, the target efficiency can be achieved even with a drop of 100 V – 150 V.



**Figure 2.** Performance of the DLC-RPC for the  $\beta$ -ray. (Left) Pulse height spectra. (Right) Detection efficiency. Efficiencies were calculated with a 20 mV signal threshold, which corresponds to a 25 fC threshold in the induced charge to the readout strip.

Next, we investigated the maximum voltage applied to the gap with the different widths of the protection cover (0.2 mm and 0.8 mm) In this measurement, the  $\beta$ -ray was not collimated and irradiated to the whole active region with O (100 kHz) of the hit rate. In both widths, the efficiency

requirement was fulfilled although the maximum operation voltages were reduced by 50 - 60 V due to the high current flowing irregularly around the strip structure. Increasing the cover width can slightly suppress such current frequency, though it also increases the dead area. Therefore, the 0.2 mm width should be selected.

Finally, long-term stability was measured. O(100 kHz) of  $\beta$ -ray was continuously irradiated to the whole region. The left plot in Figure 3 shows the operation status. The voltage was applied at 2.6 kV, which is 30 - 50 V lower than the target voltage. Discharges suddenly occurred after about 14 hours and the DLC-RPC eventually tripped after 20 hours. The discharge created a current path on the pillar, as shown in the right picture in Figure 3, and prevented further operation.



Figure 3. Status of the long-term operation. (Left) Operation voltage and measured current. (Right) Picture of the damaged spacing pillar.

We have described the measured performance is promising to fulfill all the requirements. On the other hand, the long-term instability, caused by materials inside gaps, is problematic in the MEG II experiment. Since low surface resistivity can cause such instability, it should be adjusted to safer ranges (above  $20 \text{ M}\Omega/\text{sq}$ ). Besides, the avalanche charge could gradually burn the polymer in the pillars, eventually leading to the discharges as shown in Figure 3. Ionic contamination of residuals from resist developing process could reduce the current paths. We will investigate solutions to suppress the instability.

## Acknowledgments

We are grateful for the technical support provided by the Micro-Pattern Technology workshop at CERN and for the technical advice of Rui De Oliveira. This work is supported by JSPS, Japan KAKENHI Grant Number JP21H04991, JST SPRING, Japan Grant Number JPMJSP2148.

#### References

- K. Ieki and et al., Prototype study of 0.1% X<sub>0</sub> and MHz/cm<sup>2</sup> tolerant Resistive Plate Chamber with Diamond-Like Carbon electrodes, NIM A 1064 (2024) 169375.
- [2] A.M. Baldini and et al., The design of the MEG II experiment, EPJ C 78 (2018).
- [3] K. Yamamoto and et al., *Development of ultra-low mass and high-rate capable RPC based on Diamond-Like Carbon electrodes for MEG II experiment*, *NIM A* **1054** (2023) 168450.
- [4] S. Ritt, The DRS chip: cheap waveform digitizing in the GHz range, NIM A 518 (2004) 470.